-	Тур	B L#	# Hits	Search Text	DBs	Time Stamp
1	BRS	L3	384	(method with fastener).TI. and molding	USPAT; US-PGPUE EPO; JPO; DERWENT IBM_TDB	2004/06/12 03:50 F;
2	BRS	L4	81	3 and (hook with loop)	USPAT; US-PGPUB EPO; JPO; DERWENT IBM_TDB	2004/06/12 03:49
3	BRS	L5	2009	leach.INV.	USPAT; US-PGPUB EPO; JPO; DERWENT IBM_TDB	2004/06/12 03:49
4	BRS	L6	42 -	5 and (hook and loop)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/06/12 03:49
5	BRS	L7	2891	(method with fastener) and molding	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/06/12 03:50
6	BRS	L8	578	7 and (hook and loop)	USPAT; US-PGPUB; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/06/12 03:50
7	BRS	L9	418	8 and base	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/06/12 03:50
3	BRS	L10	65	9 and neck	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/06/12 03:51
	BRS	L11	0 .	(method with velcro with fastener).TI. and molding	US-PGPUB;	004/06/12 03:52

	Comments	Error Definition	Error s	
. 1		*	0	
2		·	0	
3		-	0	•
4	-		0	·
5			0	•
6			0	
. 7			0	ŭ.
8	·		0	•
9			0	

•

a.									
	Туре	L,#	Hits	Search Text	DBs	Time Stamp			
10	BRS	L12	3 .	(method with velcro with fastener).TI.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/06/12 03:53			

•

%)

.

· · · · · · · · · · · · · · · · · · ·			
	Comments	Error Definition	Error
10			
			0